

24 SEP 1981

Potential Hazardous Waste Site

KMS
Charles A. Gazda, Chief
Compliance Section (6SA-SC)

SEP 25 1981

Bruce Elliot, Chief
General Enforcement Branch (6EG)

Site Name Kaponga TAP008089021
Location Walden, Va
Hazard No. TV1214
TDO No. E-6-8105-34

A. Field Report:

T2070-2	attached	{ } <u>not completed</u>
T2070-3 recon sampling	attached	
ISS Compliance Report	attached	
ISS Non-Notifier Report	attached	

B. §311 potential (completed by 6SA-E) yes () no (X)

1. §311 sample collected	yes ()	no (X)
2. Analytical results attached	yes ()	no (X)
3. Proposed §311 action:		

C. Were drinking water wells sampled? yes () no (X)

D. Analytical Data: no samples collected SUPERFUND FILE

1. FIT data review	attached ()	
2. Contract lab results:		DEC 23 1991
water	attached { }	REORGANIZED
soil, waste	attached { }	

3. Houston Lab results attached ()

E. Comments: no further action plannedcc: ~~Adale Mitchell (6W-6)~~

PA's from 1980 and 1981 conflict, so a Site Inspection is requested in order to resolve these conflicts. The 1980 PA indicated a potential for contamination of water supply and for a fresh spill, and sampling is requested in order to confirm or negate these possibilities

DB
0/13/81

156271

